

OCTOBER 31, 1983

MULTIPLE SHEATH CABLES

(File as Card No. 1 on Multiple Sheath Cables)

**MANUFACTURE
DISCONTINUED**

The manufacture of the following multiple sheath cables has been discontinued and it is not considered necessary to maintain complete information in the catalog.

For information on codes not listed below, see other cards on Multiple Sheath Cables.

Code	Repl by	Code	Repl by	Code	Repl by
(*)ABAM6	606B Cable	ABMM152	ABMM150	ADAC200	BHAA200 recom
(*)ABAM11	607B Cable	(*)ABMM200	ARMM200 recom	ADAC200AT	CA1911-200 recom
(*)ABAM16	608B Cable	ABMM202	ABMM200	ADAC300	CDAC300
(*)ABAM25	609B Cable	(*)ABMM300	ARMM300 recom	ADAC300AT	CDAC300AT
ABAM26	ABAM25	ABMM303	ABMM300	ADAC400	CDAC400
(*)ABAM50	610B Cable	(*)ABMM400	ARMM400 recom	ADAC400AT	CDAC400AT
ABAM51	ABAM50	ABMM404	ABMM400	ADAC450	—
(*)ABAM75	612B Cable	(*)ABMM600	ARMM600 recom	ADAC450AT	—
ABAM76	ABAM75	ABMM606	ABMM600	ADAC600	CDAC600
(*)ABAM100	611B Cable	(*)ABMM900	ARMM900 recom	ADAC600AT	CDAC600AT
ABAM101	ABAM100	ABMM909	ABMM900	ADAC900	CDAC900
(*)ABAM150	ARAM150 recom	ADAB900	CDAV900	ADAC900AT	CDAC900AT
ABAM152	ABAM150	ADAB1200	CDAV1200	ADAC1100	CDAC1100
(*)ABAM200	ARAM200 recom	ADAC25	BHAA25 recom	ADAC1200	CDAC1200
ABAM202	ABAM200	ADAC25AT	CA1911-25 recom	ADAH11	BHAH11 recom
(*)ABAM300	ARAM300 recom	ADAC50	BHAA50 recom	ADAH11BT	BHAH11BT recom
ABAM303	ABAM300	ADAC50AT	CA1911-50 recom	ADAH11GT	BHAH11 recom
(*)ABAM400	ARAM400 recom	ADAC75	BHAA75 recom	ADAH16	BHAH16 recom
ABAM404	ABAM400	ADAC75AT	CA1911-75 recom	ADAH16BT	BHAH16BT recom
(*)ABAM600	ARAM600 recom	ADAC100	BHAA100 recom	ADAH16GT	BHAH16 recom
ABAM606	ABAM600	ADAC100AT	CA1911-100 recom	ADAH25	BHAH25 recom
(*)ABMM100	ARMM100 recom	ADAC150	BHAA150 recom	ADAH25BT	BHAH25BT recom
ABMM101	ABMM100	ADAC150AT	CA1911-150 recom	ADAH25GT	BHAH25 recom
(*)ABMM150	ARMM150 recom				

(*) Codes added this issue.