

MAY 31, 1980

MULTIPLE SHEATH CABLES

(File as Card No. 13 Multiple Sheath Cables)

**MANUFACTURE
DISCONTINUED**

Code	Repl by	Code	Repl by	Code	Repl by
BKMH400MP	BKMH400UM	BKMU50	BKMH50	BKTA50GT	BKTA50MP
BKMH600MP	BKMH600UM	BKMU75	BKMH75	BKTA50MP	BKTA50UM
BKMH900MP	BKMH900UM	BKMU100	BKMH100	BKTA75	—
BKMR11	BKMA11	BKMU150	BKMH150	(*)BKTA75BT	—
BKMR16	BKMA16	BKMU200	BKMH200	BKTA75GT	BKTA75MP
BKMR25	BKMA25	BKMU300	BKMH300	BKTA75MP	BKTA75UM
BKMR50	BKMA50	BKMU400	BKMH400	BKTA75UM	—
BKMR75	BKMA75	BKMU600	BKMH600	(*)BKTA100BT	—
BKMT11	BKMG11	BKMU900	BKMH900	BKTA100GT	BKTA100MP
BKMT16	BKMG16	BKTA11	—	BKTA100MP	BKTA100UM
BKMT25	BKMG25	(*)BKTA11BT	—	BKTA150	—
BKMT50	BKMG50	BKTA11GT	BKTA11MP	(*)BKTA150BT	—
BKMT75	BKMG75	BKTA11MP	BKTA11UM	BKTA150GT	BKTA150MP
BKMT100	BKMG100	BKTA11UM	—	BKTA150MP	BKTA150UM
BKMT150	BKMG150	BKTA16	—	BKTA150UM	—
BKMT200	BKMG200	(*)BKTA16BT	—	BKTA200GT	BKTA200MP
BKMT300	BKMG300	BKTA16GT	BKTA16MP	BKTA200MP	BKTA200UM
BKMT400	BKMG400	BKTA16MP	BKTA16UM	BKTA300GT	BKTA300MP
BKMT600	BKMG600	BKTA16UM	—	BKTA300MP	BKTA300UM
BKMT900	BKMG900	(*)BKTA25BT	—	BKTA400GT	BKTA400MP
BKMU11	BKMH11	BKTA25GT	BKTA25MP	BKTA400MP	BKTA400UM
BKMU16	BKMH16	BKTA25MP	BKTA25UM		
BKMU25	BKMH25	(*)BKTA50BT	—		

(*) Codes added this issue.