

NOVEMBER 30, 1982

MULTIPLE SHEATH CABLES

(File as Card No. 17 on Multiple Sheath Cables)

**MANUFACTURE
DISCONTINUED**

Code	Repl by	Code	Repl by	Code	Repl by
BSTH11GT	—	BSTH152GT	DSTH152GT	BSTH1212GT	DSTH1212GT
BSTH16	—	BSTH202	DSTH202	BSTH1515	DSTH1515
BSTH16BT	—	BSTH202BT	DSTH202BT	BSTH1515BT	DSTH1515BT
BSTH16GT	—	BSTH202GT	DSTH202GT	BSTH1515GT	DSTH1515GT
BSTH26	—	BSTH303	DSTH303	BSTH1818	DSTH1818
BSTH26BT	—	BSTH303BT	DSTH303BT	BSTH1818BT	DSTH1818BT
BSTH26GT	—	BSTH303GT	DSTH303GT	BSTH1818GT	DSTH1818GT
BSTH51	DSTH51	BSTH404	DSTH404	BSTH2121	DSTH2121
BSTH51BT	DSTH51BT	BSTH404BT	DSTH404BT	BSTH2121BT	DSTH2121BT
BSTH51GT	DSTH51GT	BSTH404GT	DSTH404GT	BSTH2121GT	DSTH2121GT
BSTH76	DSTH76	BSTH606	DSTH606	CDMB1200	CDMV1200
BSTH76BT	DSTH76BT	BSTH606BT	DSTH606BT	CDMB1500	CDMV1500
BSTH76GT	DSTH76GT	BSTH606GT	DSTH606GT	CDMB1800	CDMV1800
BSTH101	DSTH101	BSTH909	DSTH909	(*)CDMM600	ARMM600 recom
BSTH101BT	DSTH101BT	BSTH909BT	DSTH909BT	(*)CDMM900	ARMM900 recom
BSTH101GT	DSTH101GT	BSTH909GT	DSTH909GT	(*)CDMM1200	ARMM1200 recom
BSTH152	DSTH152	BSTH1212	DSTH1212	(*)CDMM1500	—
BSTH152BT	DSTH152BT	BSTH1212BT	DSTH1212BT	(*)CDMM1800	ARMM1800 recom

(*) Codes added this issue.