

FEBRUARY 26, 1982

MULTIPLE SHEATH CABLES

(File as Card No. 18 on Multiple Sheath Cables)

**MANUFACTURE
DISCONTINUED**

Code	Repl by	Code	Repl by	Code	Repl by
CNBC303	FNBC303	(*)DKTB-2700	DKTV-2700	DSAA404	BHAA400 recom
CNBC404	FNBC404	DNBA16	GNBA16	DSAA455	DSAC455 recom
CNBC455	FNBC455	DNBA26	GNBA26	DSAA606	BHAA600 recom
CSTC51	BSTC51	DNBA51	GNBA51	DSAA909	DSAC909 recom
CSTC76	BSTC76	DNBA76	GNBA76	DSAC26	ADAC25
CSTC101	BSTC101	DNBA101	GNBA101	DSAC26AT	ADAC25AT
CSTC152	BSTC152	DNBA152	GNBA152	DSAC26BT	ADAH25BT
CSTC202	BSTC202	DNBA202	GNBA202	DSAC26GT	ADAH25
CSTC303	BSTC303	DNBA303	GNBA303	DSAC51	ADAC50
CSTC404	BSTC404	DNBC51	GNBC51	DSAC51AT	ADAC50AT
CSTC606	BSTC606	DNBC76	GNBC76	DSAC51BT	ADAH50BT
CSTC909	BSTC909	DNBC101	GNBC101	DSAC51GT	ADAH50
CSTC1212	BSTC1212	DNBC152	GNBC152	DSAC76	ADAH75
CSTC1515	BSTC1515	DNBC202	GNBC202	DSAC76AT	ADAC75AT
CSTC1818	BSTC1818	DNBC303	GNBC303	DSAC76BT	ADAH75BT
DHAB900	DHAV900	DSAA11	BHAA11 recom	DSAC76GT	ADAH75
DKMB1200	DKMV1200	DSAA16	BHAA16 recom	DSAC101	ADAC100
DKMB1500	DKMV1500	DSAA26	BHAA25 recom	DSAC101AT	ADAC100AT
DKMB1800	DKMV1800	DSAA51	BHAA50 recom	DSAC101BT	ADAH100BT
(*)DKTB-1200	DKTV-1200	DSAA76	BHAA75 recom	DSAC101GT	ADAH100
(*)DKTB-1500	DKTV-1500	DSAA101	BHAA100 recom	DSAC152	ADAC150
(*)DKTB-1800	DKTV-1800	DSAA152	BHAA150 recom	DSAC152AT	ADAC150AT
(*)DKTB-2100	DKTV-2100	DSAA202	BHAA200 recom		
(*)DKTB-2400	DKTV-2400	DSAA303	BHAA300 recom		

(*) Codes added this issue.