

MAY 31, 1980

MULTIPLE SHEATH CABLES

(File as Card No. 1A on Multiple Sheath Cables)

**MANUFACTURE
DISCONTINUED**

Code	Repl by	Code	Repl by	Code	Repl by
ADAH50	BHAH50 recom	(*)ADAH300BT	CDAH300BT	ADAH900GT	—
ADAH50BT	BHAH50BT recom	ADAH300GT	ADAH300MP	(*)ADAH900MP	CDAH900MP
ADAH50GT	BHAH50 recom	(*)ADAH300MP	CDAH300MP	(*)ADAH1100	CDAH1100
ADAH75	BHAH75 recom	(*)ADAH400	CDAH400	(*)ADAH1100MP	CDAH1100MP
ADAH75BT	BHAH75BT recom	(*)ADAH400BT	CDAH400BT	(*)ADAH1200	CDAH1200
ADAH75GT	BHAH75 recom	ADAH400GT	ADAH400MP	ADBC16	BHBA16 recom
ADAH100	BHAH100 recom	(*)ADAH400MP	CDAH400MP	ADBC16AT	CA1910-16 recom
ADAH100BT	BHAH100BT recom	ADAH450	—	ADBC25	BHBA25 recom
ADAH100GT	BHAH100 recom	ADAH450BT	—	ADBC25AT	CA1910-25 recom
ADAH150	BHAH150 recom	ADAH450GT	—	ADBC50	BHBA50 recom
ADAH150BT	BHAH150BT recom	(*)ADAH600	CDAH600	ADBC50AT	CA1910-50 recom
ADAH150GT	BHAH150 recom	(*)ADAH600BT	CDAH600BT	ADBC75	BHBA75 recom
ADAH200	BHAH200 recom	ADAH600GT	ADAH600MP	ADBC75AT	CA1910-75 recom
ADAH200BT	BHAH200BT recom	(*)ADAH600MP	CDAH600MP	ADBC100	BHBA100 recom
ADAH200GT	BHAH200 recom	(*)ADAH900	CDAH900	ADBC100AT	CA1910-100 recom
(*)ADAH300	CDAH300	(*)ADAH900BT	CDAH900BT		

(*) Codes added this issue.