

NOVEMBER 30, 1978

MULTIPLE SHEATH CABLES

(File as Card No. 2 on Multiple Sheath Cables)

MANUFACTURE
DISCONTINUED

Code	Repl by	Code	Repl by	Code	Repl by
ADBC150	BHBA150 recom	ADBH150BT	BHBH150BT recom	(*)ADMC1200	CDMC1200
ADBC150AT	CA1910-150 recom	ADBH150GT	BHBH150 recom	(*)ADMC1200AT	CDMC1200AT
ADBC200	BHBA200 recom	ADBH200	BHBH200 recom	(*)ADMC1500	CDMC1500
ADBC200AT	CA1910-200 recom	ADBH200BT	BHBH200BT recom	(*)ADMC1500AT	CDMC1500AT
ADBH6	BHBH6 recom	ADBH200GT	BHBH200 recom	(*)ADMC1800	CDMC1800
ADBH6BT	BHBH6BT recom	ADBH300GT	ADBH300MP	ADMH16	BKMH16 recom
ADBH6GT	BHBH6 recom	ADBH400GT	—	ADMH16BT	BKMH16BT recom
ADBH11	BHBH11 recom	ADBH450GT	—	ADMH16GT	BKMH16 recom
ADBH11BT	BHBH11BT recom	ADMC50	BKMA50 recom	ADMH25	BKMH25 recom
ADBH11GT	BHBH11 recom	ADMC50AT	CA1912-50 recom	ADMH25BT	BKMH25BT recom
ADBH16	BHBH16 recom	ADMC75	BKMA75 recom	ADMH25GT	BKMH25 recom
ADBH16BT	BHBH16BT recom	ADMC75AT	CA1912-75 recom	ADMH50	BKMH50 recom
ADBH16GT	BHBH16 recom	ADMC100	BKMA100 recom	ADMH50BT	BKMH50BT recom
ADBH25	BHBH25 recom	ADMC100AT	CA1912-100 recom	ADMH50GT	BKMH50 recom
ADBH25BT	BHBH25BT recom	ADMC150	BKMA150 recom	ADMH75	BKMH75 recom
ADBH25GT	BHBH25 recom	ADMC150AT	CA1912-150 recom	ADMH75BT	BKMH75BT recom
ADBH50	BHBH50 recom	ADMC200	BKMA200 recom	ADMH75GT	BLMH75 recom
ADBH50BT	BHBH50BT recom	ADMC200AT	CA1912-200 recom	ADMH100	BKMH100 recom
ADBH50GT	BHBH50 recom	(*)ADMC300	CDMC300	ADMH100BT	BKMH100BT recom
ADBH75	BHBH75 recom	(*)ADMC300AT	CDMC300AT	ADMH100GT	BKMH100 recom
ADBH75BT	BHBH75BT recom	(*)ADMC400	CDMC400	ADMH150	BKMH150 recom
ADBH75GT	BHBH75 recom	(*)ADMC400AT	CDMC400AT	ADMH150BT	BKMH150BT recom
ADBH100	BHBH100 recom	(*)ADMC600	CDMC600	ADMH150GT	BKMH150 recom
ADBH100BT	BHBH100BT recom	(*)ADMC600AT	CDMC600AT	ADMH200	BKMH200 recom
ADBH100GT	BHBH100 recom	(*)ADMC900	CDMC900		
ADBH150	BHBH150 recom	(*)ADMC900AT	CDMC900AT		

(*) Codes added this issue.