

NOVEMBER 30, 1976

MULTIPLE SHEATH CABLES

(File as Card No. 27 on Multiple Sheath Cables)

**MANUFACTURE
DISCONTINUED**

Code	Repl by	Code	Repl by	Code	Repl by
FSMC404	ADMC400 recom	FSMH51	ADMH50 recom	FSMH404GT	ADMH400GT recom
FSMC404AT	ADMC400AT recom	FSMH51BT	ADMH50BT recom	FSMH606	ADMH600 recom
FSMC404BT	ADMH400BT recom	FSMH51GT	ADMH50GT recom	FSMH606BT	ADMH600BT recom
FSMC404GT	ADMH400 recom	FSMH76	ADMH75 recom	FSMH606GT	ADMH600GT recom
FSM606	ADMC600 recom	FSMH76BT	ADMH75BT recom	FSMH909	ADMH900 recom
FSM606AT	ADMC600AT recom	FSMH76GT	ADMH75GT recom	FSMH909BT	ADMH900BT recom
FSM606BT	ADMH600BT recom	FSMH101	ADMH100 recom	FSMH909GT	ADMH900GT recom
FSMC606GT	ADMH600 recom	FSMH101BT	ADMH100BT recom	FSMH1212	ADMH1200 recom
FSMC909	ADMC900 recom	FSMH101GT	ADMH100GT recom	FSMH1212BT	ADMH1200BT recom
FSMC909AT	ADMC900AT recom	FSMH152	ADMH150 recom	FSMH1212GT	ADMH1200GT recom
FSMC909BT	ADMC900BT recom	FSMH152BT	ADMH150BT recom	FSMH1515	ADMH1500 recom
FSMC909GT	ADMH900 recom	FSMH152GT	ADMH150GT recom	FSMH1515BT	ADMH1500BT recom
FSMC1212	ADMC1200 recom	FSMH202	ADMH200 recom	FSMH1515GT	ADMH1500GT recom
FSMC1212AT	ADMC1200AT recom	FSMH202BT	ADMH200BT recom	FSMN606	ADMN600 recom
FSMC1212BT	ADMH1200BT recom	FSMH202GT	ADMH200GT recom	FSMN909	ADMN900 recom
FSMC1212GT	ADMH1200 recom	FSMH303	ADMH300 recom	FSMN1212	ADMN1200 recom
FSMC1515	ADMC1500 recom	FSMH303BT	ADMH300BT recom	FSMN1515	ADMN1500 recom
FSMC1515AT	ADMC1500AT recom	FSMH303GT	ADMH300GT recom	GNBA6	GNBL6 lead covered recom
FSMC1515BT	ADMH1500BT recom	FSMH404	ADMH400 recom	GNBA11	GNBC11 recom
FSMC1515GT	ADMH1500 recom	FSMH404BT	ADMH400BT recom	GNBA16	CA1727A,16 pair recom