

NOVEMBER 30, 1978

MULTIPLE SHEATH CABLES

(File as Card No. 3 on Multiple Sheath Cable)

MANUFACTURE
DISCONTINUED

Code	Repl by	Code	Repl by	Code	Repl by
ADMH200BT	BKMH200BT recom	ADMM600	CDMM-600	(*)ADTC600AT	CDTC600AT
ADMH200GT	BKMH200 recom	ADMM900	CDMM-900	(*)ADTC900	CDTC900
(*)ADMH300	CDMH300	ADMM1200	CDMM-1200	(*)ADTC900AT	CDTC900AT
(*)ADMH300BT	CDMH300BT	ADMM1500	CDMM-1500	(*)ADTC1200	CDTC1200
ADMH300GT	ADMH300MP	ADMM1800	CDMM-1800	(*)ADTC1200AT	CDTC1200AT
(*)ADMH300MP	CDMH300MP	ADMN600	—	(*)ADTC1500	CDTC1500
(*)ADMH400	CDMH400	ADMN900	—	(*)ADTC1500AT	CDTC1500AT
(*)ADMH400BT	CDMH400BT	ADMN1200	—	(*)ADTC1800	CDTC1800
ADMH400GT	ADMH400MP	ADMN1500	—	(*)ADTC1800AT	CDTC1800AT
(*)ADMH400MP	CDMH400MP	ADMN1800	—	(*)ADTC2100	CDTC2100
(*)ADMH600	CDMH600	ADTC50	BKTA50 recom	(*)ADTC2100AT	CDTC2100AT
(*)ADMH600BT	CDMH600BT	ADTC50AT	CA1913-50 recom	(*)ADTC2400	CDTC2400
ADMH600GT	ADMH600MP	ADTC75	BKTA75 recom	(*)ADTC2400AT	CDTC2400AT
(*)ADMH600MP	CDMH600MP	ADTC75AT	CA1913-75 recom	(*)ADTC2700	CDTC2700
(*)ADMH900	CDMH900	ADTC100	BKTA100 recom	(*)ADTC3000	CDTC3000
(*)ADMH900BT	CDMH900BT	ADTC100AT	CA1913-100 recom	(*)ADTC3600	CDTC3600
ADMH900GT	ADMH900MP	ADTC150	BKTA150 recom	ADTH25	BKTH25 recom
(*)ADMH900MP	CDMH900MP	ADTC150AT	CA1913-150 recom	ADTH25BT	BKTH25BT recom
(*)ADMH1200	CDMH1200	ADTC200	BKTA200 recom	ADTH25GT	BKTH25 recom
(*)ADMH1200BT	CDMH1200BT	ADTC200AT	CA1913-200 recom	ADTH50	BKTH50 recom
ADMH1200GT	ADMH1200MP	(*)ADTC300	CDTC300	ADTH50BT	BKTH50BT recom
(*)ADMH1200MP	CDMH1200MP	(*)ADTC300AT	CDTC300AT	ADTH50GT	BKTH50 recom
(*)ADMH1500	CDMH1500	(*)ADTC400	CDTC400	ADTH75	BKTH75 recom
(*)ADMH1500BT	CDMH1500BT	(*)ADTC400AT	CDTC400AT	ADTH75BT	BKTH75BT recom
ADMH1500GT	—	(*)ADTC600	CDTC600	ADTH75GT	BKTH75 recom

(*) Codes added this issue.