

NOVEMBER 30, 1978

MULTIPLE SHEATH CABLES

(File as Card No. 3A on Multiple Sheath Cables)

**MANUFACTURE
DISCONTINUED**

Code	Repl by	Code	Repl by	Code	Repl by
ADTH100	BKTH100 recom	(*)ADTH1200	CDTH1200	ADTM1200	CDTM-1200
ADTH100BT	BKTH100BT recom	(*)ADTH1200BT	CDTH1200BT	ADTM1500	CDTM-1500
ADTH100GT	BKTH100 recom	ADTH1200GT	ADTH1200MP	ADTM1800	CDTM-1800
ADTH150	BKTH150 recom	(*)ADTH1200MP	CDTH1200MP	ADTM2100	CDTM-2100
ADTH150BT	BKTH150BT recom	(*)ADTH1500	CDTH1500	ADTM2400	CDTM-2400
ADTH150GT	BKTH150 recom	(*)ADTH1500BT	CDTH1500BT	ADTM2700	CDTM-2700
ADTH200	BKTH200 recom	ADTH1500GT	ADTH1500MP	(*)ADTN600	ADTM600
ADTH200BT	BKTH200BT recom	(*)ADTH1500MP	CDTH1500MP	(*)ADTN900	ADTM900
ADTH200GT	BKTH200 recom	(*)ADTH1800	CDTH1800	(*)ADTN1200	ADTM1200
(*)ADTH300	CDTH300	(*)ADTH1800BT	CDTH1800BT	(*)ADTN1500	ADTM1500
(*)ADTH300BT	CDTH300BT	ADTH1800GT	ADTH1800MP	(*)ADTN1800	ADTM1800
ADTH300GT	ADTH300MP	(*)ADTH1800MP	CDTH1800MP	(*)ADTN2100	ADTM2100
(*)ADTH300MP	CDTH300MP	(*)ADTH2100	CDTH2100	(*)ADTN2400	ADTM2400
(*)ADTH400	CDTH400	(*)ADTH2100BT	CDTH2100BT	(*)ADTN2700	ADTM2700
(*)ADTH400BT	CDTH400BT	ADTH2100GT	—	AHAA11	BHAA11 recom
ADTH400GT	ADTH400MP	(*)ADTH2100MP	CDTH2100MP	AHAA11BT	BHAA11BT recom
(*)ADTH400MP	CDTH400MP	(*)ADTH2400	CDTH2400	AHAA11GT	BHAA11GT recom
(*)ADTH600	CDTH600	(*)ADTH2400BT	CDTH2400BT	AHAA16	BHAA16 recom
(*)ADTH600BT	CDTH600BT	ADTH2400GT	—	AHAA16BT	BHAA16BT recom
ADTH600GT	ADTH600MP	(*)ADTH2400MP	CDTH2400MP	AHAA16GT	BHAA16GT recom
(*)ADTH600MP	CDTH600MP	(*)ADTH2700	CDTH2700	AHAA26	BHAA25 recom
(*)ADTH900	CDTH900	(*)ADTH2700MP	—	AHAA26BT	BHAA25BT recom
(*)ADTH900BT	CDTH900BT	(*)ADTH3000	—	AHAA26GT	BHAA25GT recom
ADTH900GT	ADTH900MP	ADTM600	CDTM-600	AHAA51	BHAA50 recom
(*)ADTH900MP	CDTH900MP	ADTM900	CDTM-900	AHAA51BT	BHAA50BT recom

(*) Codes added this issue.