

FEBRUARY 26, 1982

MULTIPLE SHEATH CABLES

(File as Card No. 7A on Multiple Sheath Cables)

**MANUFACTURE
DISCONTINUED**

Code	Repl by	Code	Repl by	Code	Repl by
AJTW200	—	AKMA51GT	BKMA50GT recom	AKMG16T	BKMG16GT recom
AJTW200UM	—	AKMA76	BKMA75 recom	AKMG26	BKMG25 recom
AJTW300	—	AKMA76BT	BKMA75BT recom	AKMG26BT	BKMG25BT recom
AJTW300UM	—	AKMA76GT	BKMA75GT recom	AKMG26GT	BKMG25GT recom
AJTW400	—	AKMA101	BKMA100 recom	AKMG51	BKMG50 recom
AJTW400UM	—	AKMA101BT	BKMA100BT recom	AKMG51BT	BKMG50BT recom
AJTW600	—	AKMA101GT	BKMA100GT recom	AKMG51GT	BKMG50GT recom
(*)AJTW-600UM	—	AKMA152	BKMA 150 recom	AKMG76	BKMG75 recom
AJTW900	—	AKMA152BT	BKMA150BT recom	AKMG76BT	BKMG75BT recom
(*)AJTW-900UM	—	AKMA152GT	BKMA150GT recom	AKMG76GT	BKMG75GT recom
AKMA11	BKMA11 recom	AKMA202	BKMA200 recom	AKMG101	BKMG100 recom
AKMA11BT	BKMA11BT recom	AKMA202BT	BKMA200BT recom	AKMG101BT	BKMG100BT recom
AKMA11GT	BKMA11GT recom	AKMA202GT	BKMA200GT recom	AKMG101GT	BKMG100GT recom
AKMA16	BKMA16 recom	AKMA303	BKMA300 recom	AKMG152	BKMG150 recom
AKMA16BT	BKMA16BT recom	AKMA303BT	BKMA300BT recom	AKMG152BT	BKMG150BT recom
AKMA16GT	BKMA16GT recom	AKMA303GT	BKMA300GT recom	AKMG152GT	BKMG150GT recom
AKMA26	BKMA25 recom	AKMG11	BKMG11 recom	AKMG202	BKMG200 recom
AKMA26BT	BKMA25BT recom	AKMG11BT	BKMG11BT recom	AKMG202BT	BKMG200BT recom
AKMA26GT	BKMA25GT recom	AKMG11GT	BKMG11GT recom	AKMG202GT	BKMG200GT recom
AKMA51	BKMA50 recom	AKMG16	BKMG16 recom		
AKMA51BT	BKMA50BT recom	AKMG16BT	BKMG16BT recom		

(*) Codes added this issue.