

MAY 31, 1980

MULTIPLE SHEATH CABLES

(File as Card No. 9 on Multiple Sheath Cables)

**MANUFACTURE
DISCONTINUED**

Code	Repl by	Code	Repl by	Code	Repl by
ANCA26	BHBA25 recom	ASFA16	BKMA16 recom	BHAA16GT	BHAA16MP
ANCA51	BHBA50 recom	ASFA26	BKMA25 recom	BHAA16MP	BHAA16UM
ANCA76	BHBA75 recom	ASFA51	BKMA50 recom	BHAA16UM	—
ANCA101	BHBA100 recom	ASFA76	BKMA75 recom	(*)BHAA25BT	—
ANCA152	BHBA150 recom	ASFA101	BKMA100 recom	BHAA25GT	BHAA25MP
ANCA202	BHBA200 recom	ASFA152	BKMA150 recom	(*)BHAA50BT	—
Type ANCC	—	ASFA202	BKMA200 recom	BHAA50GT	BHAA50MP
ANDA11	BHAA11 recom	ASFA303	BKMA300 recom	BHAA75	—
ANDA16	BHAA16 recom	ASFA404	BKMA400 recom	BHAA75BT	—
ANDA26	BHAA25 recom	ASFA606	BKMA600 recom	BHAA75GT	BHAA75MP
ANDA51	BHAA50 recom	ASFA909	BKMA900 recom	BHAA75MP	BHAA75UM
ANDA76	BHAA75 recom	Type ASFC	—	BHAA75UM	—
ANDA101	BHAA100 recom	BHAA11	—	BHAA100GT	BHAA100MP
ANDA152	BHAA150 recom	(*)BHAA11BT	—	BHAA150	—
ANDA202	BHAA200 recom	BHAA11GT	BHAA11MP	BHAA150BT	—
ANDA303	BHAA300 recom	BHAA11MP	BHAA11UM	BHAA150GT	BHAA150MP
ANDA404	BHAA400 recom	BHAA11UM	—	BHAA150MP	BHAA150UM
ANDA455	DSAC455 recom	BHAA16	—		
Type ANDC	—	(*)BHAA16BT	—		

(*) Codes added this issue.