

MARCH 29, 1985

COUPLERS
(File as Card No. 1 on Couplers)

**MANUFACTURE
DISCONTINUED**

The manufacture of the following Couplers has been discontinued and it is not necessary to maintain complete information in the catalog.

For information on code numbers not listed below, see other cards on Couplers.

Code No.	Replaced by No.
23A	—
26A	—
26B	—
(*)100A	—

(*) Codes added this issue.