

FIRST CLASS MAIL

*NOTICE

Installation Engineering Handbook 30
Western Electric Company, Incorporated
Columbus Works

UIS Section 85
Dated: 9/24/82

URGENT INFORMATION SUPPLEMENT

TANDEM BLOCKING ARRANGEMENT FOR
CONVENTIONAL DISTRIBUTING FRAMES

1. GENERAL

- 1.1 This UIS is issued to correct a mounting screw size. It will be incorporated into the regular handbook section on the next reissue.

2. INSTRUCTION

- 2.1 In paragraphs 3.24, 3.25 and 3.26 change mounting screw size from 8x32x5 to 8x32x6.

1372G

Manager, Product Engineering
Control Center

Printed in U.S.A.

*NOT FOR USE OR DISCLOSURE OUTSIDE THE BELL SYSTEM
EXCEPT UNDER WRITTEN AGREEMENT
