

INTERMARKER GROUP AND INTERTRAIN TRUNKS
EQUIPMENT UNITS
EQUIPMENT DESIGN REQUIREMENTS
NO. 5 CROSSBAR SYSTEM

1. GENERAL

1.001 This addendum supplements Section 819-604-150, Issue 6.

1.002 This addendum is issued to rate the click-producing feature "Mfr Disc." for intermarker group trunks in accordance with SD-25837-01, Issue 8D, SD-25837-02, Issue 8D, SD-25838-01, Issue 6D, SD-25838-02, Issue 8D, and SD-25839-02, Issue 6D.

- (a) J23065A, List 3 — Removed
- (b) J23065B, List 4 — Removed
- (c) J23065C, List 4 — Removed
- (d) J23065F, List 4 — Removed

4. EQUIPMENT

The following changes apply to Part 4 of the section:

Under J23065A

Remove: List 3

Under J23065B

Remove: List 4

Under J23065C

Remove: List 4

Under J23065F

Change: List 2 To Read:

List 2 — Equipment and wiring required in addition to list 1 for AMA in accordance with SD-25837-02, Fig. 1.

Remove: List 4

Under J23065L

Change: List 1 To Read:

List 1 — Assembly, equipment, and wiring for two trunks arranged for SX supervision in accordance with SD-26143-01, two apparatus Fig. 1 and 3.

5. GENERAL NOTES

The following changes apply to Part 5 of the section:

Under List of "A&M Only" and "Mfr Disc." Equipment

Add:

J23065A,L3	Mfr Disc.	6	—
J23065B,L4	Mfr Disc.	6	—
J23065C,L4	Mfr Disc.	6	—
J23065F,L5	Mfr Disc.	6	—

Bell Telephone Laboratories, Incorporated

Dept 5614